# [Oct-2023 Huawei Transmission H31-311\_V2.5 Exam Practice Dumps [Q99-Q117



[Oct-2023] Huawei Transmission H31-311\_V2.5 Exam Practice Dumps 2023 H31-311\_V2.5 Premium Files Test pdf - Free Dumps Collection

# **NEW QUESTION 99**

In MSP networking, when the optical fiber is connected between sites, the east light plate of the site is connected to the west light plate of the downstream site, and these stations are connected in turn to form a ring. In this case, the direction from the toko plate of the site to the wine light plate of the downstream station is the direction of the main ring, and the direction of forming the ring is the direction of service.

- \* True
- \* Error

# **NEW QUESTION 100**

Bait-doped fiber amplifiers (EDFAs) are a key component of the new generation of optical communication systems. Which of the following is the feature of EDFA? Multiple Choice) ?

\* High gain

- \* High output meritorious service
- \* Amplification of any wavelength
- \* Low noise index

# **NEW QUESTION 101**

Which of the following is not an EVPLAN feature?

- \* bandwidth sharing
- \* Forwarding based on MAC address
- \* point-to-point, and point-to-multipoint topologies
- \* Multipoint to multipoint topology

#### **NEW QUESTION 102**

Which of the following is affected by changing the element ID of OSN3500 on NMS?

- \* Interruption of business.
- \* Restart your device.
- \* Network element communication is interrupted.
- \* NE time is out of sync.

#### **NEW QUESTION 103**

Which of the following is the basic requirement of the DWDM system in the light source?

- \* output wavelength stabilization
- \* Use the direct modulation method
- \* Low dispersion tolerance.
- \* The launch function is very high

#### **NEW QUESTION 104**

EPL services use bandwidth exclusively on the line, which is very safe. Dedicated line applications for VIP customers

- \* True
- \* Error

# **NEW QUESTION 105**

Which of the following statements about the U2000 license is incorrect?

\* Each license file corresponds to the device serial number (ESN) of one U2000 computer, so it can only be used on the corresponding computer.

\* Official U2000 licenses vary by operating system platform. You must apply for a U2000 license based on your specific operating system. (Correct answer"

- \* The U2000 license file xxxxxx is named .dat format
- \* Do not modify the license file. Otherwise, the license file will fail

# **NEW QUESTION 106**

Which of the following is the difference between an AU pointer and a TU pointer? (Multiple choice).

- \* Indicates the range
- \* The number of bits occupied by the pointer value
- \* The byte that stores the pointer value

\* Adjust units

# **NEW QUESTION 107**

In the Windows operating system, the log files of the U2000 program are stored in the () directory of the U2000 installation disk.

- \* /U2000/server
- \* /U2000/client/log
- \* /u2000/server/log
- \* /U2000/Client

#### **NEW QUESTION 108**

The SP3D board supports 63 E1 services

- \* True
- \* False

# **NEW QUESTION 109**

When the sender detects that the b6-b8 of the K2 byte is 110, it means that the sender has reported an alarm ().

- \* MS-AIS
- \* R THE
- \* R LOF
- \* MS RIF

# **NEW QUESTION 110**

The number of ODU2e signals multiplexed into the ODU3 signal is the same as the number of ODU2 signals multiplexed into the ODU3 signal

- \* yes
- \* False

# **NEW QUESTION 111**

PDM uses a polarization beam splitter to divide the laser into two vertical directions: x and y.

- \* True
- \* Error

# **NEW QUESTION 112**

Which factors determine the optical signal-to-noise ratio (OSNR) of the receiving end to a certain extent After the signal transmission in the WOM system is transmitted over a certain distance, the "oSNR" of the receiving end of the optical signal-to-noise ratio is reduced to a certain extent. Which of the following is the main cause?

- \* Use EDFA. ).
- \* Use of multi-density multiplexers and multiplexers.
- \* Do not use new optical fibers.
- \* Optical fiber attenuation is too high.

# **NEW QUESTION 113**

The segment overhead of STM-4 is () bytes/frame.

- \* 9\*9\*4
- \* 9\*8″4
- \* 9\*9\*8
- \* 9\*8

# **NEW QUESTION 114**

The clock unit can only access the external clock source as the timing signal source of the system through the external clock interface. In addition; It can also output a processed clock and provide a clock source for other devices that need timing.

- \* True
- \* False

# **NEW QUESTION 115**

Which of the following statements about the clock source are incorrect?

- \* The internal clock source has the lowest priority due to low accuracy.
- \* Typically, a branch clock is not used as a clock source for a device.
- \* Select the same SSM co-editor for all NE in the clock protection subnet
- \* If the difficultY SSM protocol is enabled, you need to set the clock source ID to correct the answer.

# **NEW QUESTION 116**

Which of the following logic function blocks are involved in processing clock signals? (Multiple choice).

- \* SPl
- \* RST
- \* MCF
- \* SETS

# **NEW QUESTION 117**

Which overhead below 112 is not ODUk overhead?

- \* PM
- \* Traditional Chinese Medicine
- \* NJO
- \* APs/PCc

Huawei H31-311\_V2.5 certification exam is a comprehensive test designed to evaluate an individual's skills and knowledge in transmission technologies. H31-311\_V2.5 exam is the latest version of HCIA-Transmission, and it tests the candidate's understanding of advanced technologies, network principles, and system architecture. The HCIA-Transmission V2.5 certification is specifically designed for candidates who want to pursue a career in the ICT industry and become a Huawei certified engineer.

Get ready to pass the H31-311\_V2.5 Exam right now using our Huawei Transmission Exam Package: https://www.examcollectionpass.com/Huawei/H31-311\_V2.5-practice-exam-dumps.html]